

**From:** [Moore, Gary](#)  
**To:** ["Gavlas, Sean"](#)  
**Subject:** F.J. Doyle Salvage  
**Date:** Wednesday, September 26, 2018 9:50:20 AM

---

Sean:

I think we should have the building inspected for asbestos even though we did not see anything at all in the building. I am trying to get information about wipe sampling for the metal on the metal building.

Also, when we go out to do the sampling for ERRS for TCLP is specific grids, we also probably need to do some sampling of other drainage ditches along Cottonwood. We should probably discuss.

Thanks

**Gary W. Moore (6SF-ER)**  
**Federal On-Scene Coordinator**  
**U.S EPA Region 6**  
**1445 Ross Ave, Suite 1200**  
**Dallas, TX 75202-2733**  
**Cell: 214.789.1627**  
**[moore.gary@epa.gov](mailto:moore.gary@epa.gov)**